

LKW

MB Sprinter Kasten 105KW

NEW

SALE

Wien, Österreich



Data & Facts

Brand	MERCEDES BENZ
Type	MB Sprinter Kasten 105KW
Machine Type	LKW
Year	2018
Milage	193164
IN	30028071
Location	Wien 1110 Wien / Österreich
Available From	DI. 21-07-2026 = ENDE DER BIETERFRIST

Price & Info

€ 2.900,00

Price excl. VAT. For cars and LCVs, the price quoted is the minimum selling price. These vehicles will be sold to the buyer with the best bid submitted.

Details

Steinschläge Vorbau und WSS, Fahrersitzpolster aufgerissen, Sicherheitsgurt mittig verdreht, Einstieg rechts rostig, B-Säule rechts Rost, Schiebetür diverse Dellen und verzogen, Seitenblinker rechts defekt, Lenkung Geräusch, Innenverkleidung Hecktüren beschädigt, Service fällig, Achsteile angerostet, Abblendlicht rechts defekt, Motorhaube beschädigt, Kupplungspedal quietscht, div. kleinere Dellen und Kratzer, Abnutzung dem Alter und der Laufleistung entsprechend

Fahrzeug fahrbereit

VERKAUF NUR AN GEWERBLICHE ANBIETER IM BLINDBIETERVERFAHREN. NUR BESTPREISANGEBOT PER MAIL BIS DIENSTAG, 21-07-2026, 11:00 UHR. DER BIETER HAT SICH SELBST ÜBER DEN TECHNISCHEN UND OPTISCHEN ZUSTAND DES FAHRZEUGES ZU INFORMIEREN. DIE BESCHREIBUNG DER MÄNGEL MUSS NICHT VOLLSTÄNDIG SEIN. UNVOLLSTÄNDIGE ODER FALSCHER ANGABEN IM INSERAT BERECHTIGEN NICHT ZUR NACHTRÄGLICHEN PREISKORREKTUR! DRUCKFEHLER VORBEHALTEN. BESICHTIGUNG VOR ANGEBOOTSABGABE ERWÜNSCHT!

Stone chips on the front fender and wheel arch, driver's seat cushion torn, seat belt twisted in the middle, rust on the right side of the door sill, rust on the right B-pillar, sliding door has various dents and is warped, right side turn signal defective, steering makes noise, interior trim on rear doors damaged, due for service, Rusted axle parts, right low beam headlight defective, damaged hood, squeaky clutch pedal, various minor dents and scratches, wear and tear consistent with age and mileage

Vehicle is roadworthy

SALE ONLY TO COMMERCIAL BUYERS VIA BLIND BIDDING. BEST PRICE OFFERS BY EMAIL ONLY UNTIL TUESDAY, JULY 21, 2026, AT 11:00 A.M. THE BIDDER IS RESPONSIBLE FOR DETERMINING THE TECHNICAL AND COSMETIC CONDITION OF THE VEHICLE. THE DESCRIPTION OF DEFECTS MAY NOT BE COMPLETE. INCOMPLETE OR INCORRECT INFORMATION IN THE LISTING DOES NOT ENTITLE THE BIDDER TO A SUBSEQUENT PRICE ADJUSTMENT! SUBJECT TO PRINTING ERRORS. INSPECTION BEFORE SUBMITTING A BID IS RECOMMENDED!

Images

If you have
any questions,
please contact:



Gerald Tichy

+43 50 626 - 8980

gerald.tichy@porr.at