


PKW

Ford Galaxy Business 2,0 EcoBlue 7Sitze 110KW

NEW

SALE Wien, Österreich



Data & Facts

Brand	FORD
Type	Ford Galaxy Business 2,0 EcoBlue 7Sitze 110KW
Machine Type	PKW
Year	2019
Milage	157415
IN	30046576
Location	Wien (Zentrale) Absberggasse 47 1100 Wien / Österreich
Available From	DI. 09-06-2026 = ENDE DER BIETERFRIST

Price & Info

€ 7.700,00

Details

§57a gültig bis 11/26, Vorbau und Windschutzscheibe Steinschläge, Türe rechts vorne Delle u. div. Kratzer, Türe links hinten div. Kratzer, Seitenwand links Lackabplatzungen und Kratzer, Heckstoßstange div. Kratzer und Schürfungen, Heckklappe Kratzer, Seitenwand rechts Kratzer, Türe rechts vorne Lackschaden an der Türkante, Kotflügel rechts Kratzer, div. kleinere Dellen und Kratzer, Abnutzung dem Alter und der Laufleistung entsprechend

Fahrzeug fahrbereit

Price excl. VAT. For cars and LCVs, the price quoted is the minimum selling price. These vehicles will be sold to the buyer with the best bid submitted.

VERKAUF NUR AN GEWERBLICHE ANBIETER IM BLINDBIETERVERFAHREN. NUR BESTPREISANGEBOT PER MAIL BIS DIENSTAG, 09-06-2026, 11:00 UHR. DER BIETER HAT SICH SELBST ÜBER DEN TECHNISCHEN UND OPTISCHEN ZUSTAND DES FAHRZEUGES ZU INFORMIEREN. DIE BESCHREIBUNG DER MÄNGEL MUSS NICHT VOLLSTÄNDIG SEIN. UNVOLLSTÄNDIGE ODER FALSCHER ANGABEN IM INSERAT BERECHTIGEN NICHT ZUR NACHTRÄGLICHEN PREISKORREKTUR! DRUCKFEHLER VORBEHALTEN. BESICHTIGUNG VOR ANGEBOTSABGABE ERWÜNSCHT!

§57a valid until 11/26, front fender and windshield have stone chips, front right door has a dent and various scratches, rear left door has various scratches, left side panel has paint chips and scratches, rear bumper has various scratches and scuffs, tailgate has scratches, right side panel: scratches; front right door: paint damage on the door edge; right fender: scratches; various minor dents and scratches; wear and tear consistent with age and mileage

Vehicle in running condition

SALE ONLY TO COMMERCIAL BUYERS VIA SEALED BID. BEST PRICE OFFERS BY EMAIL ONLY UNTIL TUESDAY, JUNE 9, 2026, 11:00 AM. THE BIDDER IS RESPONSIBLE FOR DETERMINING THE TECHNICAL AND COSMETIC CONDITION OF THE VEHICLE. THE DESCRIPTION OF DEFECTS MAY NOT BE COMPLETE. INCOMPLETE OR INCORRECT INFORMATION IN THE LISTING DOES NOT ENTITLE THE BUYER TO A SUBSEQUENT PRICE ADJUSTMENT! SUBJECT TO PRINTING ERRORS. INSPECTION BEFORE SUBMITTING A BID IS RECOMMENDED!

Images

If you have
any questions,
please contact:



Gerald Tichy

+43 50 626 - 8980

gerald.tichy@porr.at