

Ford Ranger DOKA XL 2,0TDCi 125KW

NEW

SALE Linz, Österreich



Data & Facts

Brand	FORD
Type	Ford Ranger DOKA XL 2,0TDCi 125KW
Machine Type	PKW
Year	2020
Milage	200213
IN	30047772
Location	4020 Linz / Österreich
Available From	DI. 22-09-2026 = ENDE DER BIETERFRIST

Price & Info

€ 4.900,00

Price excl. VAT. For cars and LCVs, the price quoted is the minimum selling price. These vehicles will be sold to the buyer with the best bid submitted.

Details

§57a gültig bis 01/2027, leichter Ölverlust, Partikelfilter defekt, Kupplung defekt, Getriebeölverlust, Allradantrieb funktioniert nicht, Blattfedern und Stabilisator hinten defekt, Achsträger hinten und vorne angerostet, Rahmen angerostet, Fahrzeughimmel verschmutzt, Wassereintritt Heckleuchte links hinten, Fensterleiste Hardtop hinten Lackschäden, rostig, Abdeckung WSS rechts unten fehlt, Einstieg vorne eingedrückt, Schlüssel defekt, Ersatzschlüssel fehlt, div. Roststellen, Dellen, Kratzer. Lackabplatzer, Abschürfungen, Flugrost bzw. allgemeine Gebrauchsspuren

Fahrzeug NICHT fahrbereit(Kupplung)

VERKAUF NUR AN GEWERBLICHE ANBIETER IM BLINDBIETERVERFAHREN. NUR BESTPREISANGEBOT PER MAIL BIS DIENSTAG, 22-09-2026, 11:00 UHR. DER BIETER HAT SICH SELBST ÜBER DEN TECHNISCHEN UND OPTISCHEN ZUSTAND DES FAHRZEUGES ZU INFORMIEREN. DIE BESCHREIBUNG DER MÄNGEL MUSS NICHT VOLLSTÄNDIG SEIN. UNVOLLSTÄNDIGE ODER FALSCHER ANGABEN IM INSERAT BERECHTIGEN NICHT ZUR NACHTRÄGLICHEN PREISKORREKTUR! DRUCKFEHLER VORBEHALTEN. BESICHTIGUNG VOR ANGEBOTSSABGABE ERWÜNSCHT!

S57a valid until 01/2027, slight oil leak, defective particulate filter, defective clutch, transmission oil leak, all-wheel drive not functioning, defective rear leaf springs and stabilizer bar, Rust on front and rear axle carriers, rust on frame, soiled headliner, water ingress in left rear taillight, paint damage on rear hardtop window trim, rusty, missing WSS cover on lower right, dented front door sill, defective key, missing spare key, various rust spots, dents, and scratches. Paint chips, scuffs, surface rust, and general signs of wear

Vehicle NOT roadworthy (clutch)

SALE ONLY TO COMMERCIAL BUYERS VIA SEALED-BID PROCESS. BEST PRICE OFFERS BY EMAIL ONLY UNTIL TUESDAY, SEPTEMBER 22, 2026, 11:00 AM.

THE BIDDER IS RESPONSIBLE FOR DETERMINING THE VEHICLE'S TECHNICAL AND COSMETIC CONDITION. THE DESCRIPTION OF DEFECTS NEED NOT BE EXHAUSTIVE. INCOMPLETE OR INCORRECT INFORMATION IN THE LISTING DOES NOT ENTITLE THE BIDDER TO A SUBSEQUENT PRICE ADJUSTMENT! SUBJECT TO PRINTING ERRORS. INSPECTION BEFORE SUBMITTING A BID IS RECOMMENDED!

Images

If you have
any questions,
please contact:



Gerald Tichy

+43 50 626 - 8980

gerald.tichy@porr.at