

LKW

Ford Transit DOKA Pritsche 96KW

NEW

SALE Wien, Österreich



Data & Facts

Brand	FORD
Type	Ford Transit DOKA Pritsche 96KW
Machine Type	LKW
Year	2018
Milage	121330
IN	30028023
Location	Wien 1110 Wien / Österreich
Available From	DI. 09-06-2026 = ENDE DER BIETERFRIST

Price & Info

€ 1.800,00

Price excl. VAT. For cars and LCVs, the price quoted is the minimum selling price. These vehicles will be sold to the buyer with the best bid submitted.

Details

Steinschläge Vorbau und WSS, Lenkgetriebe defekt, Bremse verschlissen, Unterboden rostig, Ladefläche gebrochen, Fahrersitz eingerissen, Sitzbank hinten eingerissen, Stoßstange vorne Kratzer, Dach bei WSS Rost, Kotflügel links Kratzer, Fahrertür Delle und Kratzer, Tür links hinten beschädigt, Kotflügel rechts Kratzer, Beifahrertür Kratzer, Tür hinten rechts Dellen und Kratzer, Celone rechts gebrochen, div. kleinere Dellen und Kratzer, Abnutzung dem Alter und der Laufleistung entsprechend

Fahrzeug BEDINGT fahrbereit

VERKAUF NUR AN GEWERBLICHE ANBIETER IM BLINDBIETERVERFAHREN. NUR BESTPREISANGEBOT PER MAIL BIS DIENSTAG, 09-06-2026, 11:00 UHR. DER BIETER HAT SICH SELBST ÜBER DEN TECHNISCHEN UND OPTISCHEN ZUSTAND DES FAHRZEUGES ZU INFORMIEREN. DIE BESCHREIBUNG DER MÄNGEL MUSS NICHT VOLLSTÄNDIG SEIN. UNVOLLSTÄNDIGE ODER FALSCHER ANGABEN IM INSERAT BERECHTIGEN NICHT ZUR NACHTRÄGLICHEN PREISKORREKTUR! DRUCKFEHLER VORBEHALTEN. BESICHTIGUNG VOR ANGEBOTSABGABE ERWÜNSCHT!

Stone chips on the front fender and wheel arch, steering gear defective, brakes worn, underbody rusty, cargo area damaged, driver's seat torn, rear bench seat torn, Front bumper scratched, roof rusted near WSS, left fender scratched, driver's door dented and scratched, left rear door damaged, right fender scratched, passenger door scratched, right rear door dented and scratched, right side panel broken, various minor dents and scratches, wear and tear consistent with age and mileage

Vehicle is CONDITIONALLY roadworthy

SALE ONLY TO COMMERCIAL BUYERS VIA SEALED-BID PROCESS. BEST PRICE OFFERS BY EMAIL ONLY UNTIL TUESDAY, 09-06-2026, 11:00 AM. THE BIDDER IS RESPONSIBLE FOR DETERMINING THE TECHNICAL AND COSMETIC CONDITION OF THE VEHICLE. THE DESCRIPTION OF DEFECTS MAY NOT BE COMPLETE. INCOMPLETE OR INCORRECT INFORMATION IN THE LISTING DOES NOT ENTITLE THE BUYER TO A SUBSEQUENT PRICE ADJUSTMENT! SUBJECT TO PRINTING ERRORS. INSPECTION BEFORE SUBMITTING A BID IS RECOMMENDED!

Images

If you have
any questions,
please contact:



Gerald Tichy

+43 50 626 - 8980

gerald.tichy@porr.at