

LKW

MB Sprinter Kasten 105KW

NEW

SALE

Wien, Österreich



Data & Facts

Brand	MERCEDES BENZ
Type	MB Sprinter Kasten 105KW
Machine Type	LKW
Year	2016
Milage	119194
IN	30017290
Location	Wien 1110 Wien / Österreich
Available From	DI. 21-07-2026 = ENDE DER BIETERFRIST

Price & Info

€ 3.800,00

Price excl. VAT. For cars and LCVs, the price quoted is the minimum selling price. These vehicles will be sold to the buyer with the best bid submitted.

Details

Steinschläge Vorbau und WSS, Ad-Blue Fehler, Reifen vorne verschlissen, Bremse hinten verschlissen, Motorträger angerostet, Glas bei Tacho fehlt, Fahrersitz aufgerissen, Armaturenbrett Loch, Motorhaube Kratzer, Stoßstange vorne beschädigt, Kühlerabdeckung Delle, Dach Kratzer, Hecktüren Delle und Kratzer, beide Kotflügel Dellen und Kratzer, Fahrertür Delle und Kratzer, Seitenwand links Delle und Kratzer, Seitenwand rechts Kratzer, Beifahrertür Delle und Kratzer, Schiebetür Delle und Kratzer, Schweller rechts Rost, div. kleinere Dellen und Kratzer, Abnutzung dem Alter und der Laufleistung entsprechend

Fahrzeug fahrbereit

VERKAUF NUR AN GEWERBLICHE ANBIETER IM BLINDBIETERVERFAHREN. NUR BESTPREISANGEBOT PER MAIL BIS DIENSTAG, 21-07-2026, 11:00 UHR. DER BIETER HAT SICH SELBST ÜBER DEN TECHNISCHEN UND OPTISCHEN ZUSTAND DES FAHRZEUGES ZU INFORMIEREN. DIE BESCHREIBUNG DER MÄNGEL MUSS NICHT VOLLSTÄNDIG SEIN. UNVOLLSTÄNDIGE ODER FALSCHER ANGABEN IM INSERAT BERECHTIGEN NICHT ZUR NACHTRÄGLICHEN PREISKORREKTUR! DRUCKFEHLER VORBEHALTEN. BESICHTIGUNG VOR ANGEBOTSSABGABE ERWÜNSCHT!

Stone chips on the front fender and WSS, AdBlue error, front tires worn, rear brakes worn, rusted engine mount, missing glass in the speedometer, torn driver's seat, hole in the dashboard, scratches on the hood, damaged front bumper, dent in the radiator grille, scratches on the roof, rear doors have dents and scratches, both fenders have dents and scratches, driver's door has dents and scratches, left side panel has dents and scratches, right side panel has scratches, passenger door has dents and scratches, sliding door has dents and scratches, right side sill has rust, various minor dents and scratches, wear and tear consistent with age and mileage

Vehicle is roadworthy

SALE ONLY TO COMMERCIAL BUYERS VIA A SEALED-BID PROCESS. BEST PRICE OFFERS BY EMAIL ONLY UNTIL TUESDAY, JULY 21, 2026, AT 11:00 A.M. THE BIDDER IS RESPONSIBLE FOR DETERMINING THE TECHNICAL AND COSMETIC CONDITION OF THE VEHICLE. THE DESCRIPTION OF DEFECTS MAY NOT BE COMPLETE. INCOMPLETE OR INCORRECT INFORMATION IN THE LISTING DOES NOT ENTITLE THE BIDDER TO A SUBSEQUENT PRICE ADJUSTMENT! SUBJECT TO PRINTING ERRORS. INSPECTION BEFORE SUBMITTING A BID IS RECOMMENDED!

Images

If you have
any questions,
please contact:



Gerald Tichy

+43 50 626 - 8980

gerald.tichy@porr.at