

LKW

VW T5 Kasten MHD 2,0TDI 132KW

NEW

SALE

Linz, Österreich



Data & Facts

Brand	VW
Type	VW T5 Kasten MHD 2,0TDI 132KW
Machine Type	LKW
Year	2015
Milage	162448
IN	30003686
Location	Pummererstrasse 17 4021 Linz / Österreich
Available From	DI. 01-09-2026 = ENDE DER BIETERFRIST

Price & Info

€ 2.500,00

Details

§57a gültig bis 02/2027, Bremse vorne und hinten angerostet, Achsträger rostig, Schiebetür Kontaktschalter def., Türgummis gerissen, Türfangband links def., Heckleuchte links Sprung, Stoßstange vorne zerkratzt, Abdeckung Armaturenbrett fehlt, Himmel verschmutzt, Seitenwand li+re , Hecktüre , mehrere große Dellen und Lackschäden, div. Roststellen, Dellen, Kratzer. Lackabplatzer, Abschürfungen, Flugrost bzw. allgemeine Gebrauchsspuren, allgemeiner Zustand dem Alter entsprechend

Fahrzeug fahrbereit

Price excl. VAT. For cars and LCVs, the price quoted is the minimum selling price. These vehicles will be sold to the buyer with the best bid submitted.

VERKAUF NUR AN GEWERBLICHE ANBIETER IM BLINDBIETERVERFAHREN. NUR BESTPREISANGEBOT PER MAIL BIS DIENSTAG, 01-09-2026, 11:00 UHR. DER BIETER HAT SICH SELBST ÜBER DEN TECHNISCHEN UND OPTISCHEN ZUSTAND DES FAHRZEUGES ZU INFORMIEREN. DIE BESCHREIBUNG DER MÄNGEL MUSS NICHT VOLLSTÄNDIG SEIN. UNVOLLSTÄNDIGE ODER FALSCHER ANGABEN IM INSERAT BERECHTIGEN NICHT ZUR NACHTRÄGLICHEN PREISKORREKTUR! DRUCKFEHLER VORBEHALTEN. BESICHTIGUNG VOR ANGEBOTSABGABE ERWÜNSCHT!

\$57a valid until 02/2027, front and rear brakes rusted, axle carrier rusty, sliding door contact switch defective, door seals torn, left door hinge broken, crack in left taillight, front bumper scratched, dashboard cover missing, headliner soiled, left and right side panels, tailgate, several large dents and paint damage, various rust spots, dents, scratches. Paint chips, scuffs, surface rust, and general signs of wear; overall condition consistent with its age

Vehicle is roadworthy

SALE ONLY TO COMMERCIAL BIDDERS VIA SEALED-BID PROCESS. BEST PRICE OFFERS BY EMAIL ONLY BY TUESDAY, SEPTEMBER 1, 2026, 11:00 AM.

THE BIDDER IS RESPONSIBLE FOR DETERMINING THE VEHICLE'S TECHNICAL AND COSMETIC CONDITION. THE DESCRIPTION OF DEFECTS NEED NOT BE EXHAUSTIVE. INCOMPLETE OR INCORRECT INFORMATION IN THE LISTING DOES NOT ENTITLE THE BIDDER TO A SUBSEQUENT PRICE ADJUSTMENT! SUBJECT TO PRINTING ERRORS. INSPECTION BEFORE SUBMITTING A BID IS RECOMMENDED!

Images

**If you have
any questions,
please contact:**



Gerald Tichy

+43 50 626 - 8980

gerald.tichy@porr.at