



LKW

# VW T6 DOKA Pritsche 110KW

NEW

SALE Wien, Österreich



## Data & Facts

Brand	VW
Type	VW T6 DOKA Pritsche 110KW
Machine Type	LKW
Year	2018
Milage	269128
IN	30039224
Location	Wien 1110 Wien / Österreich
Available From	DI. 19-05-2026 = ENDE DER BIETERFRIST

## Price & Info

€ 4.600,00

Price excl. VAT. For cars and LCVs, the price quoted is the minimum selling price. These vehicles will be sold to the buyer with the best bid submitted.

## Details

Steinschläge Vorbau und WSS, Reifen vorne verschlissen, Bremse hinten verschlissen, leichter Ölverlust, Motorträger Rost, Hinterachse Rost, Fahrersitzpolsterung eingerissen, - Motorhaube diverse Kratzer, Stoßstange Kratzer, Kotflügel links Kratzer, Fahrtür Kratzer, Tür hinten links Delle, Seitenwand links Delle und Rost, beide Türen rechts Kratzer, Seitenwand mehrere Dellen, diverse Fehlermeldungen, Abnutzung dem Alter und der Laufleistung entsprechend

Fahrzeug fahrbereit

VERKAUF NUR AN GEWERBLICHE ANBIETER IM BLINDBIETERVERFAHREN. NUR BESTPREISANGEBOT PER MAIL BIS DIENSTAG, 19-05-2026, 11:00 UHR. DER BIETER HAT SICH SELBST ÜBER DEN TECHNISCHEN UND OPTISCHEN ZUSTAND DES FAHRZEUGES ZU INFORMIEREN. DIE BESCHREIBUNG DER MÄNGEL MUSS NICHT VOLLSTÄNDIG SEIN. UNVOLLSTÄNDIGE ODER FALSCHER ANGABEN IM INSERAT BERECHTIGEN NICHT ZUR NACHTRÄGLICHEN PREISKORREKTUR! DRUCKFEHLER VORBEHALTEN. BESICHTIGUNG VOR ANGEBOTSSABGABE ERWÜNSCHT!

Stone chips on the front fender and wheel arch, front tire worn, rear brake worn, slight oil leak, rust on the engine mount, rust on the rear axle, driver's seat upholstery torn, - Various scratches on the hood, scratches on the bumper, scratches on the left fender, scratches on the driver's door, dent on the rear left door, dent and rust on the left side panel, scratches on both right doors, multiple dents on the side panel, various error messages, wear and tear consistent with age and mileage

Vehicle in running condition

SALE ONLY TO COMMERCIAL BUYERS VIA SEALED-BID PROCESS. BEST PRICE OFFERS BY EMAIL ONLY UNTIL TUESDAY, MAY 19, 2026, 11:00 AM. THE BIDDER IS RESPONSIBLE FOR DETERMINING THE TECHNICAL AND VISUAL CONDITION OF THE VEHICLE. THE DESCRIPTION OF DEFECTS MAY NOT BE COMPLETE. INCOMPLETE OR INCORRECT INFORMATION IN THE LISTING DOES NOT ENTITLE THE BUYER TO A SUBSEQUENT PRICE ADJUSTMENT! SUBJECT TO PRINTING ERRORS. INSPECTION BEFORE SUBMITTING A BID IS RECOMMENDED!

# Images

If you have  
any questions,  
please contact:



**Gerald Tichy**

+43 50 626 - 8980

[gerald.tichy@porr.at](mailto:gerald.tichy@porr.at)